




Speedo Recalibration Wiring, S14



- Use Dakota Digital SGI-5
- All switches OFF
- Push the UP/DOWN buttons to calibrate